

Memorandum

DATE:

October 15, 2002

TO:

Dan Cargill/Ecology

FROM

Scott Dwyer

RE:

Soil Concentrations of Arsenic at Long Painting

**Facility** 

The purpose of this memorandum is to demonstrate that the arsenic concentrations in the subsurface soil at the Long Painting facility at  $8025 - 10^{th}$  Avenue South, Seattle, are in compliance with the Model Toxics Control Act (MTCA) Method A soil cleanup levels.

The soil investigation completed at the Long Painting facility included 17 samples analyzed for total arsenic. The soil samples were collected across the site at depths ranging from ground surface to four feet below ground surface (Kleinfelder 2000). A depth of four feet was selected because Kleinfelder hypothesized, and Ecology concurred, that the most likely locations for soil contamination to be found was adjacent to storm drain sumps located across the facility. The sumps are completed at a depth of approximately four feet.

Analysis of the 17 soil samples from the subject site revealed the presence of arsenic at a maximum concentration of 21 mg/kg (soil boring SB-3-1 collected from a depth of four feet). This concentration exceeds the MTCA Method A soil cleanup level of 20 mg/kg. Compliance with MTCA can be demonstrated, however, based on WAC 173-340-740 (7)(e) which states:

- No single sample concentration shall be greater than two times the soil cleanup level;
- Less than ten percent of the sample concentrations shall exceed the soil cleanup levels; and
- The upper confidence interval on the true soil concentration is less than the soil cleanup level. Statistical tests shall be performed at a Type I error level of 0.05.

The following statistics were developed from the analytical laboratory reports for soil samples collected from the subject site:



Number of soil samples analyzed for arsenic	17
Number of soil samples containing detectable concentrations of arsenic	17
Minimum arsenic concentration	1.7 mg/kg
Maximum arsenic concentration	21 mg/kg
Mean arsenic concentration	5.5 mg/kg
95th percentile upper confidence limit (Land's Method)	7.63 mg/kg

## Based on these statistics, we can demonstrate that:

- (1) No single sample concentration is greater than two times the soil cleanup level. The maximum concentration was 21 mg/kg, which exceeds the cleanup level by only 1 mg/kg.
- (2) Less than ten percent of the sample concentrations exceed the soil cleanup level of 20 mg/kg. Only one of 17 samples exceeded the arsenic cleanup level, which is only 6%.
- (3) The upper confidence interval on the true soil concentration is less than the soil cleanup level at a Type I error level of 0.05. Using Ecology's MTCAStat software, we calculated the 95<sup>th</sup> percentile upper confidence limit of the arsenic concentration to be 7.63 mg/kg, which is well below the Method A soil cleanup level of 20 mg/kg. The report from the MTCAStat program is shown below (Figure 1).

Figure 1. MTCAStat Report for Arsenic in Soil at Long Painting

	Number of samples		Uncensored values	
	Uncensored	17	Mean	5,50
and the same of th	Censored		Lognormal mean	5.40
	Detection limit or PQL		Std. devn.	4.6413899
	Method detection limit		Median	4
	TOTAL	17	Min.	1,7
			· Max.	21
1	7nolludidaib fer		ral distribution?	
r-square		949 <i>1-</i> 50L	ared is: 0	,675
•	nendations: lognormal distribution.			
1	*	است أستاما وع		
1	is 0.9549. This exceeds th	e tabled val	ue of 0.892	
1	*	e tabléd val	ue of 0.892"	
1	*	e tabléd val	ue of 0.892	
1	*	e tabléd val	ue of 0.892	
1	*	e tabléd va	ue of 0.892	
W value	is 0.9549. This exceeds th		ue of 0.892	
W value	*		ue of 0.892	
W value	is 0.9549. This exceeds th		ue of 0.892	

We conclude that the concentration of arsenic in the soil at the Long Painting facility is in compliance with MTCA and further investigation or remediation is not necessary.

## Reference

Kleinfelder. 2000. Site Investigation Report, Long Painting Company, 8025 – 10<sup>th</sup> Avenue South, Seattle, Washington. Prepared for Long Painting Company. Prepared by Kleinfelder, Inc., Bellevue, Washington. Kleinfelder Project Number 60-204601.